

# **Product Data Sheet**

Updated : March 1996 Supersedes: November 1993

### **Product Description**

DP100 clear epoxy adhesive is a clear room temperature curing, two part epoxy adhesive supplied in 3M Duo-Pak cartridge for use with the 3M EPX Applicator.

### DP100 offers the following features:

Fast curing with handling strength achieved in 15 minutes at room temperature.

A clear epoxy adhesive with high flow and excellent impact resistance.

1:1 premix system.

Machineable.

Suitable for bonding clear substrates, potting and encapsulating.

### **Physical Properties** Not for specification purposes

	2005 5005		
	BASE	ACCELERATOR	
Base	Modified Epoxy	Modified Mercaptan	
Specific Gravity	1.16	1.15	
opcome Gravity			
Viscosity	11,500	13,500	
(cP at 27°C)	,	,	
Colour	Clear	Clear	
Work Life	3-5 minutes at 24°C		
Handling Strength	15 minutes at 23°C		
Full Strength	24 hours (test full perfo	rmance at one week).	
Shelf Life	15 months from date of	espatch by 3M when stored in the	
	original carton at 21°C	(70°F) & 50 % Relative Humidity	

### **Perform** Characte Not for spec

teristics ecification purposes (0.8mm) at 24°C. 3.5 N/cm (2 piw)	nance	T-Peel Strength	Measured on abraded, steel	
			,	

Date: March 1996 EPX Clear Epoxy Adhesive

DP100

Performance Characteristics (Cont...) Not for specification purposes **Overlap Shear Strength** 

The following strength values were obtained with DP100 when tested after 5 day cure cycle at 24°C.

Substrates solvent wiped, abraded and solvent wiped prior to bonding.

	MPa	psi
Galvanised Steel	6.7	900
Cold Rolled Steel	6.9	1000
FPL Etched Aluminium	9.0	1300
Copper	6.6	950
Stainless Steel	6.2	750
Brass	4.8	700
Acrylic	1.9	280
PVČ	2.3	330
Polycarbonate	2.1	310
Neoprene/Steel	0.1	5
SBR/Steel	0.4	60
ABS	3.6	520
FRP	6.6	950

Durability

Percent of bond strength remaining after exposure to 90% relative humidity/32°C for 90 days.

All materials were solvent wiped/abraded/solvent wiped prior to bonding.

Aluminium	100	Aluminium Primed with EC1945 B/A	100
Steel	100	Steel Primed with EC1945 B/A	100
ABS	100	FRP	100

3M Primer EC1945 B/A was applied by dip-coating

Metals were 1.6mm thick Plastics were 3mm thick

## **Electrical Properties**

Dielectric Strength (Volts/mm)	4.1 x 10 <sup>4</sup>	
Volume Resistivity (Ohms/cm)	2.7 x 10 <sup>14</sup>	

## **Thermal Properties**

Thermal Conductivity W/m°C	Coefficient of Thermal Expansion (cm/cm/°C)
0.180	- 50°C to 30°C 60 x 10 <sup>-6</sup>
	50°C to 110°C 209 x 10 <sup>-6</sup>

### **Storage Conditions**

Store product at 16 to 27°C for maximum storage life. High temperatures reduce normal storage life.

Rotate stock on a "first infirst out" basis.

Date: March 1996 EPX Clear Epoxy Adhesive DP100

# Directions for Use /Clean Up

Place the cartridge into the 3M EPX Applicator and clip into position.

Remove the resealable cap.

Expel a small quantity of adhesive and ensure both components flow freely.

Attach correct mixer nozzle (this should have 20 or more elements).

Dispense the adhesive as required.

When finished either leave the nozzle in place and store, or remove the nozzle, wipe clean the tip, and replace cap.

To re-start after storage remove the old nozzle with cured adhesive and re-fit a new nozzle, or remove the cap and fit a new nozzle.

### **Surface Preparation:**

The degree of surface preparation depends on the bond strength required and the environment likely to be encountered by the bonded structure. For most plastics solvent wiping with 3M VHB surface cleaner, followed by abrasion with 3M Scotchbrite 7447, followed by a further solvent wipe until clean, will give good performance (except for acetal, polyethylene and polypropylene and some other low surface energy materials). This also applies to powder coat paints and other stoved paint systems.

The same surface preparation will also give good adhesion to metal surfaces. The objective is to remove loosely attached surface films such as oils, waxes, dusts, mill-scale, loose paints and all other

surface contaminants in addition to enhancing mechanical adhesion. Gritblasting using a clean, fine grit also offers excellent adhesion on many metallic

Where humid environments are likely to be encountered by metallic substrates we recommend additional priming with 3M Scotch-Weld 3901. Alternatively, chemical conversion coating techniques combined with priming can offer the best durability.

### Clean-Up:

substrates.

Excess uncured adhesive can be removed with the following solvents:

3M VHB Surface Cleaner (mild alcohol based cleaner) 3M Scotch-Grip Solvent No2. (Ketone blend) 3M Industrial Cleaner (Aerosol).

# Health & Safety Information

#### **Precautions:**

Causes severe eye irritation; may cause permanent eye damage. May cause sensitisation by skin contact. Avoid contact with skin and eyes. Wear suitable gloves and eye/face protection. Launder contaminated clothing before re-use. Avoid prolonged breathing of vapours.

Avoid inhalation of dust when grinding or cutting cured material.

# First Aid:

### **Eye Contact:**

Immediately flush eyes with copious amounts of water for at least 15 minutes, holding eyes open. Call a physician.

#### **Skin Contact:**

Wash immediately with plenty of soap and water.

For further Health and Safety Information please contact the Toxicology Department at the Bracknell Head Office on (0344) 858000.

3M, Scotch-Weld and EPX are trademarks of the 3M Company.

Values presented have been determined by standard test methods and are average values not to be used for specification purposes. Our recommendations on the use of our products are based on tests believed to be reliable but we would ask that you conduct your own tests to determine their suitability for your applications.

This is because 3M cannot accept any responsibility or liability direct or consequential for loss or damage caused as a result of our recommendations.



**Specialty Tapes & Adhesives** 

Customer Service :

Tel 0161 236 8500 Fax 0161 237 1105 3M Ireland 3M House, Adelphi Centre, Upper Georges Street, Dun Laoghaire,Co. Dublin, Ireland © 3M United Kingdom PLC 1996

Tel (01) 280 3555 Fax (01) 280 3509

Customer Service:

3M United Kingdom PLC 3M House, 28 Great Jackson Street, Manchester, M15 4PA