



FLEXIBLE PRECISION FOR HIGH QUALITY PLATE MOUNTING



Consult our online tool for plate related foam advice



tesa.com/foamadvisor

tesa Softprint® Foam Hardnesses

X-Soft		Soft		Medium		Medium-Hard		Hard	
Screen 40%	Screen 10%	Screen 40%	Screen 10%	Screen 40%	Screen 10%	Screen 40%	Screen 10%	Screen 40%	Screen 10%
Solid	Font neg.	Solid	Font neg.	Solid	Font neg.	Solid	Font neg.	Solid	Font neg.

Tips for Optimum Plate Mounting

Cleaning



Plate cleaning

Clean back of new or used plate of dust, grease, or other contamination using a suitable solvent.



Cylinder/sleeve cleaning

Clean per manufacturer recommendations and wipe dry with clean cloth.

Mounting



Tape mounting

Apply the tape in a sweeping motion, line by line. Use a squeegee for best results.



Plate mounting

Mount plate with rubber roller, at least on the leading and trailing edge. This will give a better bond than just by hand.

Demounting



Plate demounting

Remove plate first, then remove the tape slowly at a flat angle.



Tape demounting